General Environmental Incident Summary

Incident: 3806 Date/Time Notice: 7/3/2015 0952 DEM Incident No:

Responsible Party: CEI Electrical Contractors

Date Incident: 7/2/2015 Time Incident: 1630 Duration: 5 minutes

County: Adams Twp: 130 Rng: 95 Sec: 32 Qtr: SW SE NW

Lat: 46.04313 Long: -102.60280 Method: Navigation quality GPS

Location Description: Collection line on the Thunder Spirit Wind Project. Drive three miles north on

2nd St NE from HWY 12, turn right onto 4th AVE NE travel one mile to newly constructed access road, turn south traveling 0.6 miles to underground

collection construction site.

Submitted By: John Hollingsworth Affiliation: Project Owner

Address: 30 W Superior St

Suite 200

City: Duluth State: MN Zip: 55802

Received By:

Contact Person: Art Wiltgen

2675 Overland Ave Billings, MT 59102

Distance Nearest Occupied Building: 0.75 Miles Release Contained: Yes

Type of Incident: hydraulic line failure

Description of Released Contaminant: Hydraulic Oil

Volume Spilled: 10.00 gallons Ag Related: No

EPA Extremely Hazardous Substance: Unknown Reported to NRC: Unknown

Cause of Incident:

A hydraulic line broke inside the engine compartment of a trenching machine.

Risk Evaluation:

Minimal health hazard to skin.

of Fatalities: 0 # of Injuries: 0 Affected Medium: 03 - soil

Potential Environmental Impacts:

Minimal environment to soil due to guick response time.

Action Taken or Planned:

Numerous spill kits were deployed from the equipment and vehicles. Multiple oil absorbent pads cleaned oil inside the piece of equipment. Soil was excavated with rubber tired back hoe and staged in 55 gallon drums until picked up by Clean Harbors.

Wastes Disposal Location: Clean Harbors landfill.

Agencies Involved:

Updates

Date: 7/15/2015 Status: Reviewed - No Action Required Author: Suess, Bill

Updated Volume:

Notes:

Due to the small amount of material and rapid response of the contractor, no follow-up is needed.